

Salem Lakes Association Eurasian Water Milfoil Management Dive Report

Date: 7/27/19 Time: 8:30 – 11:30

Weather / Cloud Cover: Clear Temperature: 75

Winds (MPH, Direction): Variable 1 to 4

People participating (names): Dennis Bond, Saturn Roblee, & Ross Ogilvie

Tag index	Way-point name (temporary)	# of EWM plants found/Removed	Identifier (Buoy, Yellow flag, none)	Bottom Barrier (Number, Size)	Rebar (Number, length)	Depth (ft)
SLY001		0				
SLA009		0		previous		
SLY004	184	1	Y	previous		
SLY005	185	3	Y	previous		
SLY006	186	1	Y			
SLA017	187	6	Red Buoy	Needed		
SLY007	188	1	Y			3
SLA008		0				
SLY008	189	2	Y			5
SLA007		0				
SLA018	190	1	Red Buoy			8
SLY009	191	1	Y			
SLY010	192	1	Y			
SLA019	193	1	Red Buoy			
SLY011	194	1	Y			
SLY012	195	1	Y			
SLA020	196	11	Red Buoy	Needed		8
SLA021	197	2 not yet removed	Red Buoy			8
SLA022	198	2 not yet removed	Red Buoy			8

Goal for today: Survey from SLA001 (South of Hayward brook) to SLA016 (Clyde entrance).

Notes for the day: Surveyed and removed EWM plants from SLY001 (south of Hayward brook) south to SLA022 (roughly ~300 ft north of the boat launch).

A total of 31 EWM plants removed between SLY001 and SLA022. Four EWM plants remain at and need to be removed at SLA021 and SLA022.

Recommendations for next dive: Two Sections of barrier are needed at SLA017 and SLA020. These barriers should be about the same size as previous sections placed (3 sheets x 23 ft) . Need to remove 4 EWM plants at SLA021 and SLA022.
