

BHCC Route Repair Report

Route Name : Gossamer
Formation Name : Picture Window
Area Name : Monster
Region Name : Mount Rushmore
Grade : 5.7
Repair Date : 08/02/16
Rpaired By : Ron Yahne
Steve Wilger

Route Repair Notes : This route had drop in anchors that were getting serious wear grooves. Used Dremel to cut them off.

Hardware Installed : Anchor	Route
Belay Assembly	Belay Assembly
Anchor Assembly	10mm Coeur Hanger
2 8mm Oval Quick Link	12mm Coeur Hanger
4 8mm Chain	
Rappel Ring	
7mm Oval Quick Link	
7mm Chain	
10mm Coeur Hanger	
12mm Coeur Hanger	
Hardware Removed : Anchor	Route
2 Drop in anchors	

Hardware Notes : Need to go back and replace chain with rap rings on this anchor.