

BHCC Route Repair Report

Route Name : Evarete
Formation Name : Evarete
Area Name : Sylvan Lake
Region Name : Custer State Park
Grade : 5.7
Repair Date : 07/01/16
Rpaired By : Chris Hirsch

Route Repair Notes : An easy classic that gets a fair amount of traffic. 5 spaced bolts lead to the 2 bolt anchored summit.

Hardware Installed : Anchor

2 Belay Assembly
Anchor Assembly
3 8mm Oval Quick Link
4 8mm Chain
2 Rappel Ring
7mm Oval Quick Link
7mm Chain
10mm Coeur Hanger
12mm Coeur Hanger

Route

5 Belay Assembly
10mm Coeur Hanger
12mm Coeur Hanger

Hardware Removed : Anchor

2 5/16" threaded nail drive anchors
2 SMC hangers
2 Quick links
Webbing

Route

5 1/4" threaded nail drive bolts
5 SMC hangers

Hardware Notes :