

BHCC Route Repair Report

Route Name :
Formation Name : Practice Rock
Area Name : Outlets
Region Name : Custer State Park
Grade :
Repair Date : 07/01/16
Rpaired By : Chris Hirsch

Route Repair Notes : Daryl advised that a few sets of these TR anchors needed replacing, Installed bolts with hangers only. No rap stations.

Hardware Installed :	Anchor	Route	
	7 Belay Assembly		Belay Assembly
	Anchor Assembly		10mm Coeur Hanger
	8mm Oval Quick Link		12mm Coeur Hanger
	8mm Chain		
	Rappel Ring		
	7mm Oval Quick Link		
	7mm Chain		
	10mm Coeur Hanger		
	12mm Coeur Hanger		

Hardware Removed :	Anchor	Route
	2 3/8" wedge bolts	
	2 Metolius hangers	
	4 3/8" threaded nail drive bolts	
	4 Metolius hangers	

Hardware Notes :