

BHCC Route Repair Report

Route Name : Rockin' Harder
Formation Name : Inner Outlet
Area Name : Outlets
Region Name : Custer State Park
Grade : 5.10+
Repair Date : 07/15/16
Rpaired By : Chris Hirsch

Route Repair Notes : Well protected classic that still had buttonheads. First couple bolts were already replaced by us when we did Hardrocker. Crux bolt above roof was already replaced by someone. They used a five piece bolt and it looked fine, so I left it.

Hardware Installed : Anchor

Belay Assembly
Anchor Assembly
8mm Oval Quick Link
8mm Chain
Rappel Ring
7mm Oval Quick Link
7mm Chain
10mm Coeur Hanger
12mm Coeur Hanger

Route

9 Belay Assembly
10mm Coeur Hanger
12mm Coeur Hanger

Hardware Removed : Anchor

Route

9 5/16" x 1 1/4" buttonheads
9 Metolius hangers

Hardware Notes :