

BHCC Route Repair Report

Route Name : Critical View
Formation Name : Critical View
Area Name : South Seas
Region Name : Mount Rushmore
Grade : 5.10
Repair Date : 07/26/16
Rpaired By : Ron Yahne

Route Repair Notes : Existing bolts still in good shape. Removed 1st bolt which was 5 ft off ground since the belay platform was erected.

Hardware Installed : Anchor

Belay Assembly
Anchor Assembly
4 8mm Oval Quick Link
8 8mm Chain
Rappel Ring
7mm Oval Quick Link
7mm Chain
10mm Coeur Hanger
12mm Coeur Hanger

Route

Belay Assembly
10mm Coeur Hanger
12mm Coeur Hanger

Hardware Removed : Anchor

1/2 inch lap links
Chain

Route

Hardware Notes :