

# BHCC Route Repair Report

Route Name : Bikinis and B52s (Valdez Overhang)  
Formation Name : Birthday Rock  
Area Name : Chopping Block  
Region Name : Mount Rushmore  
Grade : 5.9  
Repair Date : 07/28/16  
Rpaired By : Ron Yahne

Route Repair Notes : This route had drop in anchors that were getting serious wear grooves. Used Dremel to cut them off.

Hardware Installed : Anchor

Belay Assembly  
Anchor Assembly  
2 8mm Oval Quick Link  
8mm Chain  
2 Rappel Ring  
7mm Oval Quick Link  
7mm Chain  
10mm Coeur Hanger  
12mm Coeur Hanger

Route

Belay Assembly  
10mm Coeur Hanger  
12mm Coeur Hanger

Hardware Removed : Anchor

2 Drop in anchors

Route

Hardware Notes :