

BHCC Route Repair Report

Route Name : The Buck Stops Here
Formation Name : Truman Tower
Area Name : Emancipation
Region Name : Mount Rushmore
Grade : 5.11-
Repair Date : 10/01/16
Rpaired By : Travis Rypkema

Route Repair Notes : Added anchor at the top of first and second pitches of The Buck Stops Here. Was only able to remove one of the 5/16 button heads. Still in place: 6- 5/16" buttonheads and 4- SMC hangers.

Hardware Installed : Anchor	Route
4 Belay Assembly	Belay Assembly
Anchor Assembly	10mm Coeur Hanger
8 8mm Oval Quick Link	12mm Coeur Hanger
14 8mm Chain	
Rappel Ring	
7mm Oval Quick Link	
7mm Chain	
10mm Coeur Hanger	
12mm Coeur Hanger	
Hardware Removed : Anchor	Route
1 5/16" buttonheads	
1 SMC hangers	

Hardware Notes : Additional tools (notched lost arrows) needed to get the existing and remaining bolts out. My crowbar was not the right tool.