

# BHCC Route Repair Report

Route Name : Ocean Gypsy  
Formation Name : Vertigo View  
Area Name : Outlets  
Region Name : Custer State Park  
Grade : 5.7/5.9  
Repair Date : 10/16/16  
Rpaired By : Chris Hirsch

Route Repair Notes : An old Piana line (5.9), and a 5.7 variation, both on the NW corner of Vertigo View. The anchor had already been replaced with one bolt, so I used that. Also, for some reason we had an odd number of rap rings, so I had the last one. And given the location of the new bolt and reusing an old hole, it worked best to go with a rap ring setup. Luckily there was a nice Omega Pacific ring left behind. Still equalizes nicely and the non-BHCC ring can be swapped out later.

## Hardware Installed : Anchor

1 Belay Assembly  
1 Anchor Assembly  
3 8mm Oval Quick Link  
7 8mm Chain  
1 Rappel Ring  
7mm Oval Quick Link  
7mm Chain  
10mm Coeur Hanger  
12mm Coeur Hanger

## Route

4 Belay Assembly  
10mm Coeur Hanger  
12mm Coeur Hanger

## Hardware Removed : Anchor

2 1/4 button head bolts  
2 SMC hangers

## Route

4 1/4 button head bolts  
4 SMC hangers

Hardware Notes : Need to relace non-BHCC ring.