

Going Down To Harlem With A Turd In My Shorts 5.8 Moster Area (Rushmore)

Ron Yahne and Jason McNabb on 8/22/11

The route is a nice 5.8 that had a poor/rusting anchor setup (The anchor was leaving large rust streaks on the rock) and sported a 1/4" button head to go along with solid 3/8" bolts. We replaced the anchor and last bolt and also swapped out a rusted washer with a stainless washer on the second to last bolt. We pulled and patched the previous bolt and anchor.

Bolt On Route:

Previous Hardware:

1/4" by 1.25" non-stainless compression bolt and non-stainless Leeper Hanger

BHCC Stainless Hardware Installed:

Fixe Triplex Bolt

Petzl Coeur Hanger

Anchor:

Previous Hardware:

1/2" non-stainless Rawl Five Piece bolt

1/2" non-stainless wedge bolt

No hangers on bolts. The 5/16" non-stainless chain was connected directly to the bolts with washers and a nut.....really rusty.

BHCC Hardware Installed:

Fixe Triplex Bolt (x2)

Petzl Coeur Hanger (x1)

Fixe Top Hanger (x1)

7mm quick links (x3)

7mm chain links (x5....4 on anchor plus 1 for cutting)

