## Salem Lakes Association Eurasian Water Milfoil Management Dive Report

Date:8	te:8/4/19			Time:9:30 AM			
Weather	/ Cloud Cov	ver:Clea	rTe	emperature:	69 Deg	F_	
Winds (N	1PH, Directi	on):Varia	ble 0-5 MPF	·			
People pa	articipating	(names):_E	d Wells, Sati	urn Roblee, R	oss Ogilvie, Pa	ula	
Staples, Fo	rrest Hammo	ond, Jim Sulliv	van, Sherry Su	ıllivan, Clair R	oberts, Lisa		
Worden, N	∕like Worden		·				
Tag index	Way-point	# of EWM	Identifier	Bottom	Rebar	Depth	
	name	plants	(Buoy,	Barrier	(Number,	(ft)	
	(temporar	found/	Yellow flag,	(Number,	length)		
	y)	Removed	none)	Size)			
SLA018	198	Many Trimmed	green	19	6	10.5	
SLA021	199	Many Trimmed	red	19	6	10.5	
SLA017	200	Many Trimmed	Orange (removed)	Same as above	Same as above	10.5	
SLA020	201	Many	Green	Same as	Same as	10.5	
		Trimmed	(removed)	above	above		
SLA019	202	Many	Orange	Same as	Same as	10.5	
		Trimmed	(removed)	above	above		
Goals for	today:_Harv	esting and	Placing Bar	rier around	SLA017,		
SLA018, 9	SLA019, and	SLA021					
Notes for	the day:						
			Jse Air tanks		wo more		
Barriers a	at least 19 ft	t long along	side of the	barriers plac	ced today		