

BHCC Route Repair Report

Route Name : Old Number 8
Formation Name : Reef #1
Area Name : South Seas
Region Name : Mount Rushmore
Grade : 5.8
Repair Date : 09/08/16
Rpaired By : Ron Yahne

Route Repair Notes : Anchor was old 3/8 bolts and chain. Replaced bolts but not chain since there are 3 other rappel anchors close by.

Hardware Installed : Anchor

2 Belay Assembly
Anchor Assembly
8mm Oval Quick Link
8mm Chain
Rappel Ring
7mm Oval Quick Link
7mm Chain
10mm Coeur Hanger
12mm Coeur Hanger

Route

Belay Assembly
10mm Coeur Hanger
12mm Coeur Hanger

Hardware Removed : Anchor

2 3/8 bolts
2 Hangers
Chain

Route

Hardware Notes :