

BHCC Route Repair Report-Limestone

Route Name : France By Chance
Formation Name : North Canyon Wall
Area Name : Falling Rock
Region Name : Rapid City
Grade : 5.10b
Repair Date :
Rpaired By :

Route Repair Notes :

Hardware Installed : Anchor

Wave Bolt
Oval Quick Link
Rappel Ring

Route

7 Wave Bolt

Hardware Removed : Anchor

Route

Hardware Notes :